IN THE UNITED STATES PATENT & TRADEMARK OFFICE

ATTORNEY DOCKET NUMBER: 200209193-1

IN RE APPLICATION OF: U.S. Patent No. 7,136,957

USPTO CONFIRMATION CODE: 6631

APPLICATION NO.: 10/808,881

FILED: Mar. 24, 2004

EXAMINER: Gopal C. Ray

GROUP ART UNIT: 2111

FOR: DEVICE BANDWIDTH MANAGEMENT USING A BUS CONFIGURATION MULTIPLEXER

37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

Sir:

The following is a request for a certificate of correction in Serial Number 10/808.881, now Patent Number 7.136.957.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

Ш	All errors were the fault of the USPTO, no fee required. In the event that a further
fee	e is required, please charge the amount to Deposit Account No. 082025.

All errors were the fault of the applicant and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

In column 15, line 17, in Claim 9, delete "module," and insert - - module - -, therefor.

(Amendment to claims filed on Jun. 15, 2006, page 6, in Claim 9, line 4)

In column 16, line 46, in Claim 19, delete "bus;." and insert - - bus. - -, therefor. (Amendment to claims filed on Jun. 15, 2006, page 9, in Claim 19, line 10)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

May 20, 2010 DATE /David A. Plettner/ Name: David A. Plettner Registration No.: 36,241

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY Intellectual Property Administration 3404 E. Harmony Road, Mail Stop 35 Fort Collins CO 80528-9599

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 7,136,957

APPLICATION NO. : 10/808,881

ISSUE DATE : Nov. 14, 2006

INVENTOR(S) : Kevin M. Somervill, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 15, line 17, in Claim 9, delete "module," and insert - - module - -, therefor,

In column 16, line 46, in Claim 19, delete "bus;," and insert - - bus. - -, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

HEWLETT-PACKARD COMPANY Intellectual Property Administration P. O. Box 272400 Fort Collins, Colorado, 80527-2400

This collection of information is required by 37 CPR 1322, and 1.232, not 1.234. The information is required to obtain or retain a benefit by the peaks which is to file rand by the CSP(10 process) as application Confidentiality is governed by \$1 U.S.C. 122 and 37 CPR 14.1 This collection is estimated to take 1 of hour to complete, including globustup, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time born require to complete this form undoor suggestions for reducing this better, doubted by sent or the Cliffer Homeston Office, U.S. Pattest and Tackman Office, U.S. Pattest and Tack